

# Quick optical source characterization on the Agilent OSA

- Characterization of various types of optical sources
- One-button testing for DFB's, Fabry-Perot and LED's
- Measurement automation



# Agilent's optical spectrum analyzers offer automated optical source and laser characterization

Laser and LED sources are key components for enabling transmission of information in fiberoptic systems. To ensure proper operation of sources in fiberoptic systems, key parameters need to be measured.

R&D and manufacturing engineers will appreciate the quick and accurate characterization of optical sources provided by the source test application. This application provides the highest level of measurement automation possible, minimizing user interaction. Simplified test setup and fast measurement speed improves throughput in manufacturing. Additionally, statistical trace calculations allows the user to measure mean wavelength (center of mass), FWHM (full width half max), and sigma on any active trace.

# Ease of setup

Characterization of optical sources using the source test application is fast and easy. The application is selected through the applications menu (figure 1). The setup screen (figure 2) allows the user to select the span, and sensitivity which minimizes the amount of noise, and peak excursion that determines which side modes are included in the measure-

ments. The Pk density/noise marker reference measures the power spectral density of the LED at the peak wavelength. All of this is available while still having access to all OSA front-panel functionality.

The source test application can also be fully controlled via GPIB, making it ideally suited for fast paced manufacturing environments.




Figure 1. Applications Menu




Figure 2. Source Test Measurement Setup

For the DFB lasers the application provides the following parameters: mode offset, stop band, center offset, peak wavelength, peak amplitude, bandwidth and SMSR (side mode suppression ratio).




Figure 3. DFB Source Test Display

For the Fabry-Perot laser measurement parameters are: mean wavelength, peak wavelength, mode spacing (in both nm and GHz), FWHM, peak amplitude, total power, and sigma.




Figure 4. Fabry-Perot Using Line Markers

# **Displaying and Documenting Results**

Once the measurement has been completed the results are quickly displayed. Results may be printed both in tabular and graphical form.

Line Markers may be used in conjunction with any source test to include the desired portions of the trace. Figure 4 shows line markers used to include specific modes for a Fabry-Perot laser.

For an LED source, the measurement parameters are: peak wavelength, sigma, FWHM, 3 dB width, total power, and peak density.

The source test application is a standard feature on all 8614xB OSAs.

A simple firmware upgrade adds the source test application to existing 8614x OSAs, at no additional cost. Please contact your local Agilent representative for further information.

For performance specifications, please refer to the 8614xB optical spectrum analyzer family technical specifications (Agilent Literature # 5980-0177E).




Figure 5. LED Display

# **Agilent Technologies'**

## Test and Measurement Support, Services, and Assistance

Agilent Technologies aims to maximize the value you receive, while minimizing your risk and problems. We strive to ensure that you get the test and measurement capabilities you paid for and obtain the support you need. Our extensive support resources and services can help you choose the right Agilent products for your applications and apply them successfully. Every instrument and system we sell has a global warranty. Support is available for at least five years beyond the production life of the product. Two concepts underlie Agilent's overall support policy: "Our Promise" and "Your Advantage."

#### Our Promise

Our Promise means your Agilent test and measurement equipment will meet its advertised performance and functionality. When you are choosing new equipment, we will help you with product information, including realistic performance specifications and practical recommendations from experienced test engineers. When you use Agilent equipment, we can verify that it works properly, help with product operation, and provide basic measurement assistance for the use of specified capabilities, at no extra cost upon request. Many self-help tools are available.

#### Your Advantage

Your Advantage means that Agilent offers a wide range of additional expert test and measurement services, which you can purchase according to your unique technical and business needs. Solve problems efficiently and gain a competitive edge by contracting with us for calibration, extra-cost upgrades, out-of-warranty repairs, and on-site education and training, as well as design, system integration, project management, and other professional engineering services. Experienced Agilent engineers and technicians worldwide can help you maximize your productivity, optimize the return on investment of your Agilent instruments and systems, and obtain dependable measurement accuracy for the life of those products.

By internet, phone, or fax, get assistance with all your test & measurement needs.

## Online assistance:

www.agilent.com/comms/lightwave

# Phone or Fax

**United States:** 

(tel) 1 800 452 4844

#### Canada:

(tel) 1 877 894 4414 (fax) (905) 282 6495

# Europe:

(tel) (31 20) 547 2323 (fax) (31 20) 547 2390

# Japan:

(tel) (81) 426 56 7832 (fax) (81) 426 56 7840

# Latin America:

(tel) (305) 269 7500 (fax) (305) 269 7599

## Australia:

(tel) 1 800 629 485 (fax) (61 3) 9210 5947

# New Zealand:

(tel) 0 800 738 378 (fax) 64 4 495 8950

### Asia Pacific:

(tel) (852) 3197 7777 (fax) (852) 2506 9284

Product specifications and descriptions in this document subject to change without notice.

Copyright © 2000 Agilent Technologies Printed in USA December 15, 2000 5988-1030EN

